

Figure 1: Concentration of Metals (Cr, Cu, Ni, Pb, Zn, As; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.




Figure 2: Concentration of Metals (Cd, Hg, Ag; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.

Date: 12/7/2016






Figure 3: Concentration of Total Organic Carbon (TOC) (mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.




Figure 4: Concentration of Tributyltin (TBT) (µg TBT/kg; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.

Date: 12/7/2016






Figure 5: Concentration of Metals and Metalloid (Cr, Cu, Ni, Pb, Zn, As; mean +SD) in sediment samples collected from Cumulative Impact Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.




Figure 6: Concentration of Metals (Cd, Hg, Ag; mean +SD) in sediment samples collected from Cumulative Impact Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.

Date: 12/7/2016






Figure 7: Concentration of Total Organic Carbon (TOC) (mg/kg dry weight; mean +SD) in sediment samples collected from Cumulative Impact Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.




Figure 8: Concentration of Tributyltin (µg TBT/kg; mean +SD) in sediment samples collected from Cumulative Impact Sediment Chemistry Monitoring for ESC CMP Vd in June 2016.

Source: H:\Team\EM\GMS Projects\0175086 CEDD EM&A for South Brothers\02

Deliverable \07 CMP Monthly Report \46th (June 2016)

Date: 12/7/2016






Figure 9: Levels of pH (mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016.




Figure 10: Levels of Turbidity (NTU; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016

Source: H:\Team\EM\GMS Projects\0175086 CEDD EM&A for South Brothers\02

Deliverable \07 CMP Monthly Report \46th (June 2016)

Date: 12/7/2016






Figure 11: Levels of Dissolved Oxygen (% saturation; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016




Figure 12: Levels of Dissolved Oxygen (mg/L; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016

Date: 12/7/2016






Figure 13: Levels of Temperature (°C; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016.




Figure 14: Levels of Salinity (ppt; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016.

Date: 12/7/2016






Figure 15: Levels of Suspended Solids (mg/L; mean +SD) recorded from Water Quality Monitoring during Capping of SB CMP 2 in June 2016




Figure 16: Level of Ammonia (mg/L; mean + SD) recorded from Water Quality Monitoring during Capping for SB CMP 2 in June 2016.

Date: 12/7/2016






Figure 17: Level of TIN (mg/L; mean + SD) recorded from Water Quality Monitoring during Capping for SB CMP 2 in June 2016




Figure 18: Level of BOD₅ (mg-O₂/L; mean + SD) recorded from Water Quality Monitoring during Capping for SB CMP 2 in June 2016.

12/7/2016 Date:

