

Figure 1: Level of pH recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.




Figure 2: Level of Dissolved Oxygen (DO) (% saturation; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.

Date: March 2017






Figure 3: Concentration of Dissolved Oxygen (DO) (mg/L; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.




Figure 4: Level of Temperature (°C; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.

Date: March 2017







Figure 5: Level of Salinity (ppt; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.






Figure 6: Levels of Turbidity (NTU; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.

Date: March 2017






Figure 7: Concentration of Copper, Zinc, Arsenic and Nickel (µg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.




Figure 8: Concentration of Total Inorganic Nitrogen (TIN) and Ammonia Nitrogen (NH3-N) (μg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.

Date: March 2017



Routine Water Quality Monitoring Results for Biochemical Oxygen Demand (BOD₀) February 2017 25 20 1.5 0.5 Reference Impact Intermediate Ma Wan

Figure 9: Level of Biochemical Oxygen Demand (BOD5) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.




Figure 10: Concentration of Suspended Solids (SS) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP Vd in February 2017.

Source: H:\Team\EM\GMS Projects\0175086 CEDD EM&A for South Brothers\02 Deliverable\07 CMP Monthly Report\54th (February 2017)

Date: March 2017

