Annex C

Graphical Presentations




Figure 1: Level of pH recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.




Figure 2: Level of Dissolved Oxygen (DO) (% saturation; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Date: September 2019






Figure 3: Concentration of Dissolved Oxygen (DO) (mg/L; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Routine Water Quality Monitoring for ESC CMP V - August 2019 35.00 25.00 20.00 10.00 Reference Impact Station Reference Impact Station

Figure 4: Level of Temperature (°C; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02 Deliverable\05 CMP Monthly Report\August 2019)

Date: September 2019






Figure 5: Level of Salinity (ppt; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Routine Water Quality Monitoring for ESC CMP V - August 2019




Figure 6: Levels of Turbidity (NTU; mean + SD) recorded during Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02 Deliverable\05 CMP Monthly Report\August 2019)

Date: September 2019






Figure 7: Concentration of Arsenic, Chromium, Nickel, Lead, Copper and Zinc (μg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.




Figure 8: Concentration of Total Inorganic Nitrogen (TIN) and Ammonia Nitrogen (NH3-N) $(\mu g/L; mean + SD)$ in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Source: H:\Team\EM\GMS Projects\0400720 CEDD CMP EM&A 2017-2020\02
Deliverable\05 CMP Monthly Report\August 2019)

Date: September 2019

Environmental
Resources
Management




Figure 9: Level of Biochemical Oxygen Demand (BOD₅) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.




Figure 10: Concentration of Suspended Solids (SS) (mg/L; mean + SD) in water samples collected from Routine Water Quality Monitoring for disposal operations at ESC CMP V in August 2019.

Date: September 2019






Figure 11: Concentration of Metals and Metalloid (Cr, Cu, Ni, Pb, Zn, As; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in August 2019.




Figure 12: Concentration of Metals (Cd, Hg, Ag; mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in August 2019.

Date: September 2019






Figure 13: Concentration of Total Organic Carbon (TOC) (mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in August 2019.




Figure 14: Concentration of Tributyltin (TBT) (μg TBT/kg; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in August 2019.

Date: September 2019






Figure 15: Concentration of Low and High Molecular Weight Polycyclic Aromatic Hydrocarbons (PAHs) (mg/kg dry weight; mean +SD) in sediment samples collected from Pit Specific Sediment Chemistry Monitoring for ESC CMP Vd in August 2019.

Date: September 2019






Figure 16: Concentration of Metals (Cr, Cu, Ni, Pb, Zn, As; mean +SD) in sediment samples collected from Sediment Chemistry after a Major Storm for ESC CMPs in August 2019.




Figure 17: Concentration of Metals (Cd, Hg, Ag; mean +SD) in sediment samples collected from Sediment Chemistry after a Major Storm for ESC CMPs in August 2019.

Date: September 2019

